

Site # A1190, Evergreen Oil

NOV #	Occurrence Date	Regulation	Comments from Enforcement	Status
A49076	5/22/2007	1-301	5 confirmed complaints	Resolved
A49078	3/3/2008	1-301	H-801 thermal oxidizer failure - odors	Resolved
A49079	3/5/2008	1-301	Odors covering several square miles	Resolved
A49088	3/28/2011	2-1-307	Source test NTV-940, excess NOx and PM10	Resolved
A49089	12/30/2011	2-1-307	ST >60 days past startup 10/31/11	Resolved
A49096	10/17/2012	2-1-307	NOx emissions, ST#NTV-1191	Resolved
A49099	2/7/2013	2-1-307	NOx emissions 93.8ppm st#NTV-1242	Resolved
A49100	6/14/2013	1-301	5 confirmed odor complaints	Resolved
A53204	Issued 10/7/2013	8-5-307	8-5-307.1 RCA	Pending
A53206	Issued 11/19/2013	1-301	8 confirmed complaints - TK800 overflow	Pending

Penalty Amount
1,000.00
1,000.00
2,000.00
2,500.00
2,500.00
2,500.00
2,500.00
3,000.00
Pending
Pending